

## Case Study #18

**Client Category:** Hydrocarbon contaminated soil  
**Location:** Dade county, Florida, U.S.A.  
**Problem:** An underground leaking motor oil storage tank went unnoticed and unemptied for 15 years.  
**Contamination Size:** Two batches of excavated soil were contaminated with motor oil.

**Batch #1** 208 cubic yards      **18,000 ppm**  
**Batch #2** 178 cubic yards      **8,530 ppm**

**Custom Treatment:** Soil was treated separately with 2 gallons of **Custom HC** per cubic yard. Nutrients were added according to recommendations and aeration was provided.

